# Technical Bulletin IUI-SOL-ADAPTER AUSEASI Direct Link Adapter



## **Issue severity**

- High. Act immediately
- Medium. Bosch Security Systems strongly recommends you take the action(s) described below.
- ∠ Low. Advisory

### **Products affected**

- ► ICP-SOL2-P
- ► ICP-SOL3-P
- ► ICP-SOL2-APR
- ► ICP-SOL3-APR
- ▶ IUI-SOL-TS4
- ► IUI-SOL-ADAPTER

#### May 23, 2017

#### Issue

When connecting to the old testing units of IUI-SOL-TS4 (4.3" Touchscreen codepad), panel firmware upgrade via IUI-SOL-ADAPTER (DLA) fails, the heartbeat LED on panel goes off.

#### Resolution

Disconnect the 4.3" Touchscreen codepad with the system, DLA can upgrade panel's firmware successfully.







Bosch Security Systems, Inc.

130 Perinton Parkway
Fairport, NY 14450 USA

www.boschsecurity.com