Rotary Address Switches
June 22, 2010

Issue Severity:

☐ **High:** Act immediately

☐ **Medium:** Bosch Security Systems, Inc. strongly recommends you take the action(s) described below.

☒ **Low:** Advisory

Products Affected:

- D7044/D7044M Single-Input Modules
- D7052 Dual-Input Module
- D7053 Input-Output Module
- FMM-7045/FMM-7045-D Addressable Manual Stations

1.0   Issue

With the affected products listed above, manufactured in July 2010 or later, the system only reads the rotary address switches when the system powers on. Address changes made with the system already powered on are not recognized by the system.

Modules manufactured in July 2010 or later are identified with **H/W:V2** on the product label.

2.0   Resolution

Configure the module addresses with the system powered off, or cycle system power to get the system to recognize rotary address switch changes. Power the system off before connecting new MUX modules to the system.

BOSCH

WPP