

# Ethernet Communication Modules

Affected Products: B426, B426-M

## OUI change

In the transition from Bosch to Radionix, we have made a change to the Organizationally Unique Identifier (OUI), which would identify the company related to the MAC Address. There were some B426 / B426-M modules where the new MAC Address that was printed on the label did not match the MAC Address loaded into the module. These can be identified by a label on the outside of the box that shows R260003. The units still operate as expected, they just have the following information to be aware of:

- The MAC Address on the label of this unit does not match what the actual MAC Address is in the unit.
- The unit still has a unique MAC Address using the previous OUI from Bosch.
- If you need to know the MAC Address for a specific installation, it can be found in the DHCP server if one is used or simply use a unit that does not have this label on the box.